



DATE: 4/2018

TOPIC: Installation Instruction / OCM System Reset

VEHICLE: 2018 Jeep Wrangler JL

The OCM (Occupant Classification Monitor) within the new JL seat is highly sensitive to movement. Because of this sensitivity, there is a chance that the OCM light will remain on after completing a Katzkin leather installation and returning the seats to the vehicle. Follow these instructions as outlined, and you may not encounter this issue.

If you do encounter this issue, the Wrangler must be taken to an FCA dealership for a reset after the completed installation. Only the dealerships will have the tools necessary for the system reset.

Please note that only Katzkin leather interiors have been tested and approved by FCA / Mopar.

OCM Light



Battery Disconnection:

Before beginning the retrim process, it is important that the negative battery cable is disconnected from the battery. Once the battery is disconnected, isolate the negative battery cable to ensure it will not come in contact with any grounding surface. A waiting period of ten minutes will be necessary before any work can begin on the vehicle.

OCM Disconnection:

Gently remove the plug from the sensor when pulling the seat out of the vehicle. Avoid any unnecessary movement to the sensor while the seat is out of the vehicle. Keep the seat secure while transporting and do not drop the seat on the floor or workstation.

