



DATE: January 25, 2021

TOPIC: 2021 Installation Tip

It has been brought to our attention there is a potential issue when performing service work on the new 2021 F-150s.

Before starting any work on the F-150, we highly recommend disconnecting the Negative Battery cable. If the seats are removed and ignition key engaged without the battery disconnected first, it will result in a systems lockup rendering the vehicle inoperable. If this system lockup occurs, it will require the Dealership to reflash the computer before the vehicle will be operable again.

Be sure to reinstall and reconnect all seat connections before reconnecting the battery and starting the truck.