



DATE: August 25, 2020

TOPIC: 2007-18 Jeep Wrangler JK 4-Door, Rear 60% cushion

In certain instances, a customer may notice that there is “sag” in the middle section of the rear seat (60%).

If the vehicle owner carries any kind of cargo directly on the seat with or without the lean backs folded, or prolonged adult passenger use of the middle rear 60% cushion, the foam will begin to cave in (Fig.1). The rear 60% cushion has unsupported foam on the underside (see Fig.2).

This issue is not related to the Katzkin produced leather seat cover and the corrective action will involve work with the foam directly.



(Fig.1)



(Fig.2)